

TSAP-DOS driver	TSAP-Win driver
lint__.dll	Not possible (LPT)
linp__.dll	Not possible (LPT)
lint001.dll	LINTAB 1 (IBRit), COM1
lint002.dll	LINTAB 1 (IBRit), COM2
lint01_.dll	Not possible (LPT)
linp01_.dll	Not possible (LPT)
lint02_.dll	Not possible (LPT)
linp02_.dll	Not possible (LPT)
lint03_.dll	Not possible (LPT)
linp03_.dll	Not possible (LPT)
lint03f.dll	Not possible (LPT)
lint04f.dll	Not possible (LPT)
lint05_.dll	Not possible (LPT)
lins__1.dll	LINTAB 4 (540/42.0mm/x10) -> 7.778, COM1
lins__2.dll	LINTAB 4 (540/42.0mm/x10) -> 7.778, COM2
lins011.dll	LINTAB 4 (2048/42.0mm/x4) -> 5.127, COM1
lins012.dll	LINTAB 4 (2048/42.0mm/x4) -> 5.127, COM2
lins021.dll	LINTAB 4 (2048/42.0mm/x4) -> 5.127, COM1
lins022.dll	LINTAB 4 (2048/42.0mm/x4) -> 5.127, COM2
lins031.dll	LINTAB 4 (500/5.0mm/x1) -> 10.000, COM1
lins032.dll	LINTAB 4 (500/5.0mm/x1) -> 10.000, COM2
lins061.dll	LINTAB 4 (500/5mm/x4) -> 2.500, COM1
lins062.dll	LINTAB 4 (500/5mm/x4) -> 2.500, COM2
lins071.dll	LINTAB 4 (2000/5mm/x4) -> 0.625, COM1
lins072.dll	LINTAB 4 (2000/5mm/x4) -> 0.625, COM2
aniol1.dll	Aniol, COM1
aniol2.dll	Aniol, COM1
heiden1.dll	Heidenhain, COM1
heiden2.dll	Heidenhain, COM2
ivo1.dll	NE 202 (Irion & Vossler), COM1
ivo2.dll	NE 202 (Irion & Vossler), COM2
heussn.dll	Not possible (LPT)
keybord.dll	Not necessary, keyboard input integrated in TSAP
kutsr11.dll	Kutschenreuther, COM1
kutsr12.dll	Kutschenreuther, COM2
velme11.dll	Velmex, COM1
velme12.dll	Velmex, COM2
innsb11.dll	Innsbruck (Nicolussi), COM1
innsb12.dll	Innsbruck (Nicolussi), COM2

**Important:**

- Please check, whether the calibration of your system is correct.
- Please note that TSAP-Win does not support the parallel connection (LPT) anymore. If necessary ask for a hardware upgrade of your measurement table.